MACHINE SURVEY REPORT

Designed By ME Consultancy Ltd.
07540850757
designedbyme@btinternet.com
www.designedbymeconsultancy.com

MACHINE SURVEY INFORMATION

Client Name:	xxxxx	**Machine:**	Narrow Band Saw
Site Name:	xxxxx	**Make & Model:**	Scheppach Basato 5.2
Post Code:	xxxx xxx	**Serial Number:**	xxxx
Job Reference:	xx – xxx - xxxx	**ID Number:**	001
Room Number/Name:	xxx	**Acc. Number:**	xx-xxx-xxx

SAFETY SIGNAGE FITTED AND VISABLE

Ear Protection:	Eye Protection:	Respiratory Mask:	Hand Protection:	Hot works:
No	Yes	N/A	N/A	N/A

	STATUS:	COMMENTS:
Micro Switches:	Working	Fully working
Foot/Knee stop switch:	Working	Good condition
Key Switch:	Working	Good condition
Lights:	-	N/A
Machine Secured to Floor or Bench:	Yes	Fully secure
Isolator Present:	Yes	Within permitted distance and named
Isolator Lockable:	Yes	-
LEV fitted:	Tested	Fully working and tested
Maintenance book/log available:	No	-
Condition of supply cable:	-	Withing conduit
Machine guard fitted:	Yes	Good condition
Fence fitted:	Yes	Good Consition
Cross slide:	No	Not present

MECHANICAL COMMENTS:

General Wear: Very good condition	**Bearings:** Good condition	**Drive Belt:** Good condition
Does Machine Run Correctly: Yes	**Does Machine Stop Within 10 Seconds as per BS4163 and PUWER:** Yes	

Comments on any work carried out on the machine:

Full clean, check as required.
Blade in good condition.

Reported to Client:	Is Remedial Work Required:	Additional Parts Used or fitted:	Continuation page used (PTO):
N/A	No	No	No

Engineers Name:	Engineer's signature:	Date:
Mark R. Elwell		XX XX XXXX

MACHINE SURVEY REPORT
(Continuation Page)

Designed By ME Consultancy Ltd.
07540850757
designedbyme@btinternet.com
www.designedbymeconsultancy.com

Further comments as required: